

**Absolute Auction
Complete Liquidation
Virtual, Live Broadcast & Timed Auctions
Blue Mountain Mulch/Dumpster Express
Wed., August 12, 2026 - 9:00 AM Eastern
Aston, Pennsylvania**

Notice: The owners of Blue Mountain Mulch and Dumpster Express, both wholly owned subsidiaries of Blue Mountain Construction Services, LLC, have decided to cease operations of these two companies, and completely liquidate all assets related to those entities at Absolute Auction. Blue Mountain Construction, LLC will continue to operate without interruption or change, while offering the finest construction services in the area. All items will be sold at Absolute Auction without minimums or reserves. This is a very unique 2-industry auction of well-maintained equipment, please plan to attend!

Location: The auction will be held at the Blue Mountain Mulch facility at 21 Crozerville Road, Aston, Pennsylvania 19014 (Please Note: There will be NO LIVE BIDDING onsite)

<u>LIVE, VIRTUAL AUCTION:</u> This auction is being conducted via <i>LIVE, VIRTUAL ONLINE ONLY</i>. <i>There will be NO LIVE BIDDING FROM THE SITE. ADDITIONALLY, there will be NO PAYMENTS accepted at the auction site! Payment must be paid either by wire transfer or credit card.</i>
--

Terms: Complete payment immediately after receipt of invoice by wire transfer or credit card only. Credit card payments will be charged a 3% processing fee.

Online Bidding: Live internet bidding will be provided by Proxibid. Proxibid will charge an Internet Service Provider Fee of 5% to the successful internet bidder for items over \$10,000 and 10% for items \$10,000 and under, for each lot purchased on-line. All bidders are required to register to bid through Proxibid.

Title Fee: There will be a \$75 fee per title.

Sales Tax: Since the items being sold were not normally sold in the course of this business, the Commonwealth of Pennsylvania considers this an isolated sale and does not require the auction company to collect sales tax.

Removal: After complete payment, items may be removed on weekdays from 8:00am until 4:00pm. All items must be removed by Wednesday, August 19, 2026 at 4:00pm. The site will be closed on Saturday and Sunday.

Dumpster Extended Loadout: An Extended Loadout of an additional week will be granted to buyers who purchase larger quantities of dumpster containers.

Sale Site Phone: (800) Bid-N-Buy • **Sale Site Fax:** (888) 859-8958

PA Auction License No: AY000281

- 1 _____ 2012 DOOSAN Model P185WYM-T4i Portable Air Compressor, s/n 441939UFWD76, powered by Yanmar diesel engine. In good condition. (Meter Reads 3,248 Hours) (Unit #B-122)
- 2 _____ 2013 DOOSAN Model P185WJD-T4i, 185CFM Skid Mounted Air Compressor, s/n 453789UDXD75, powered by JD diesel engine. (Meter Reads 1,896 Hours) (Unit #B-58)
- 3 _____ 2015 FORD Model F-150XLT, 4x4 Crew Cab Pickup Truck, VIN# 1FTEW1EF7FFB98508, powered by 5.0L, V-8 gas engine and automatic transmission, equipped with 5'6" bed, tri-fold tonneau cover, keyless entry, running boards, power windows and locks, cruise control, air conditioning, and 265/70R17 tires. In good condition with good tires. (Odometer Reads 230,748 Miles)
- 4 _____ 2008 INTERNATIONAL Model 4300 SBA Extended Cab Service Truck, VIN# 1HTMMAAL98J690344, powered by MaxxForce DT466 diesel engine and Eaton 6 speed transmission, equipped with Knapheide 11' open utility body, Auto Crane 6406H, 6,400 lb 3-section, 10'4" – 20'4" service crane with umbilical remote, Vanair hydraulic air compressor (0,194 hours), air hose and oxygen/acetylene hose reels, (2) hydraulic stabilizers, air brakes, 25,999 lb GVWR, aluminum wheels, power windows and locks, air conditioning, and 11R22.5 tires. In good condition with good tires. (Odometer Reads 158,207 Miles) (Approximately 5,000 Miles on Crate Engine and New Clutch – No Documentation) (Driver Door Locks Upon Exit) (Unit #B-12)
- 5 _____ 2006 FORD Model F-350XL Super Duty 4x4 Mulch Delivery Dump Truck, VIN# 2FDWF37506ED92173, powered by Triton 5.4L gas engine and automatic transmission, equipped with 12' steel dump body with 45" sides, barn doors, and tarp, electric hoist, 13,000 lb GVWR, dual rear wheels, air conditioning, and 245/75R17 tires. In good condition with good tires. (Odometer Reads 045,374 Miles) (New Dump Body Installed in 2015) (Unit #B-41)
- 6 _____ 2000 FORD Model F-650 Single Axle Dump Truck, VIN# 3FDNF65H1YMA44387, powered by Cat diesel engine and Spicer 5 speed transmission, equipped with 11' steel dump body, manual tarp, spring suspension, 17,500 lb rear axle, 8,500 lb front axle, 26,000 lb GVWR, tow package with electric, hydraulic brakes, air conditioning, and 10R22.5 tires. In good condition with good tires. (Odometer Reads 107,020 Miles) (Dump Body Fair to Good) (Unit #115)
- 7 _____ 2017 MACK Model GU713 Tri-Axle Dump Truck, VIN# 1M2AX09C8HM032319, powered by Mack MP8-425, 425HP diesel engine and Maxitorque ES, T310M, 10 speed transmission, equipped with Beau Roc 17'6" heated steel dump body, bed vibrator, power tarp, single chute, camelback spring suspension, 46,000 lb rears, 18,000 lb front axle, 20,000 lb lift axle, 3-stage engine brake, inter-axle lock, aluminum wheels, power heated mirrors, power windows and locks, cruise control, air conditioning, 315/80R22.5 front and lift tires, and 11R24.5 rear tires. In good condition with good tires. (Odometer Reads 202,846 Miles) (Emissions Altered) (Unit #B-70)
- 8 _____ 2017 MACK Model GU713 Tri-Axle Dump Truck, VIN# 1M2AX07C0HM032432, powered by Mack MP8, 425HP diesel engine and Allison automatic transmission, equipped with Bibeau 17'6" steel dump body, bed vibrator (not hooked up), power tarp, camelback suspension, 46,000 lb rears, 18,000 lb front axle, 20,000 lb lift axle, 3-stage engine brake, inter-axle lock, aluminum wheels, power heated mirrors, power windows and locks, cruise control, air conditioning, 315/80R22.5 front and lift tires, and 11R24.5 rear tires. In good condition with good tires. (Odometer Reads 482,442 Miles) (Meter Reads 16,442 Hours) (Emissions Altered) (Unit #B-71)

- 9 _____ 2022 KENWORTH Model T270 Single Axle Hooklift Truck, VIN# 2NKHHM6X2NM474130, powered by Paccar PX-7, 325HP diesel engine and Allison automatic transmission, equipped with Stellar Slider 20-S hook lift hoist, 20,000 lb capacity, 36"-54" hydraulic adjusting hook height, 10' – 14' container length capability, Roll Rite tarp, spring suspension, 26,000 lb GVWR, engine brake, differential lock, air brakes, aluminum wheels, air conditioning, cruise control, and 11R22.5 tires. In good to very good condition with good to very good tires. (Odometer Reads 76,498 Miles) (Meter Reads 4,003 Hours) (Rear Air but No Glad Hands or Pintle Hitch) (Unit #B-174)
- 10 _____ 2020 MACK Model GR64B Granite Tri-Axle Roll Off Truck, VIN# 1M2GR3GC4LM012005, powered by Mack MP8, 425HP diesel engine and Allison automatic transmission, equipped with 2019 American ARB-75-22-SM, 75,000 lb roll off hoist, 22' rails, power tarp, 46,000 lb rears, 18,000 lb front axle, 3-stage engine brake, inter-axle lock, camelback spring suspension, aluminum wheels, power windows and locks, cruise control, air conditioning, 315/80R22.5 front and lift tires, and 11R24.5 rear tires. In good condition with good tires. (Odometer Reads 177,105 Miles) (Reconstructed Title) (Unit #T-1) (Emissions Altered)
- 11 _____ 2020 MACK Model GR64F Granite Tri-Axle Roll Off Truck, VIN# 1M2GR3GC6LM015214, powered by Mack MP8, 425HP diesel engine and Allison automatic transmission, equipped with American ARB-75-22-SM, 75,000 lb roll off hoist, 22' rails, Roll Rite power tarp, 46,000 lb rears, 12,350 lb front axle, 3-stage engine brake, inter-axle lock, camelback spring suspension, aluminum wheels, heated mirrors, power windows and locks, cruise control, air conditioning, and 11R24.5 tires. In good condition with good tires. (Odometer Reads 222,848 Miles) (Reman Transmission Installed 2025 – No Documentation) (Unit# T-2) (Emissions Altered) (New Tarp Installed July 2026)
- 12 _____ 2018 KENWORTH Model T880 Tandem Axle Truck Tractor, VIN# 1XKZD49X4JJ180134, powered by Cummins ISX15, 500HP diesel engine and Eaton Fuller 10 speed transmission, equipped with wetline system, 40,000 lb rears, 13,200 lb front axle, 53,200 lb GVWR, air ride suspension, air slide 5th wheel, full locking differential, 3-stage engine brake, single frame, 190" wheelbase, aluminum wheels, power mirrors, locks, and windows, cruise control, air conditioning, and 11R22.5 tires. In good condition with good tires. (Odometer Reads 303,891 Miles) (Cracked Windshield) (Unit #B-73)
- 13 _____ 2017 MACK Model CXU613 Pinnacle Tandem Axle Truck Tractor, VIN# 1M1AW07Y5HM079460, powered by Mack MP8, 505HP diesel engine and Eaton Fuller 10 speed transmission, equipped with wetline system, 40,000 lb rears, 12,000 lb front axle, air ride suspension, air slide 5th wheel, 3-stage engine brake, single frame, 180" wheelbase, aluminum front and steel rear wheels, power heated mirrors, power windows and locks, cruise control, air conditioning, 11R22.5 front and 11R24.5 rear tires. In good condition with good tires. (Odometer Reads 168,515) (New Radiator September 2025) (Emissions Altered) (Unit #B-74)
- 14 _____ 2016 MACK Model CXU613 Pinnacle Tandem Axle Truck Tractor, VIN# 1M1AW07YXGM053449, powered by Mack MP8, 505HP diesel engine and Eaton Fuller 10 speed transmission, equipped with wetline system, 40,000 lb rears, 12,000 lb front axle, air ride suspension, air slide 5th wheel, 3-stage engine brake, single frame, 202" wheelbase, steel and aluminum wheels, air conditioning, and 11R22.5 tires. In good condition with good tires. (Odometer Reads 307,451 Miles) (Meter Reads 3,399 Hours) (Unit #B-75)
- 15 _____ 2021 DORSEY Model CW45, 45' Tandem Axle Walking Floor Trailer, VIN# 7KYCW4527MED20420, equipped with Keith walking floor, Load Backer ejector apron, side roll tarp, screen barn doors, 66,290 lb GVWR, spring suspension, steel wheels, and 11R22.5 tires. In good condition with good tires. (Unit #B-78)

- 16 _____ 2013 PEERLESS Model 45-CTSSF, 45' Tandem Axle Walking Floor Trailer, VIN# 1PLE04521DPG58031, equipped with Keith walking floor, Load Backer ejector apron, sliding tandems, 65,000 lb GVWR, air ride suspension, side roll tarp, aluminum wheels, and 11R24.5 tires. In good condition with good tires. (25,000 lb Axles) (Unit #B-81)
- 17 _____ 2007 HYUNDAI Model V12530152-AJRS, 53' Tandem Axle Van Trailer, VIN# 3H3V532C57T082050, equipped with smooth side aluminum, sliding tandems, Transtex side wind deflector, 65,000 lb GVWR, and 295/75R22.5 tires. In good condition with good tires. (Unit #B-48)
- 18 _____ 2007 HYUNDAI Model V12530152-4JRS, 53' Tandem Axle Van Trailer, VIN# 3H3V532C57T389041, equipped with smooth side aluminum, sliding tandems, Transtex side wind deflector, 65,000 lb GVWR, and 295/75R22.5 tires. In good condition with good tires. (Unit #B-44)
- 19A _____ 2020 BOBCAT Model T740 Crawler Skid Steer Loader, s/n B3CA17776, powered by Bobcat diesel engine and 2-speed hydrostatic transmission, equipped with general purpose loader bucket, power coupler, high flow hydraulics, selectable joystick controls, enclosed ROPS cab with air conditioning, and 18" rubber tracks. In good condition with good tracks. (Meter Reads 2,021 Hours) (Unit #B033) (RESERVED FOR USE DURING LOADOUT THRU WEDNESDAY, AUGUST 19, 2026 @ 3:00PM)
- 19 _____ 2010 MERCEDES Sprinter Van, VIN# WD3PF4CC5A5467312, powered by diesel engine and automatic transmission, equipped with dual rear wheels. In fair condition with good tires. (No Brakes)
- 20 _____ 2021 VOLVO Model L90H Rubber Tired Loader, s/n 625916, powered by Volvo diesel engine and powershift transmission, equipped with general purpose loader bucket, hydraulic coupler, front auxiliary hydraulics, fingertip bucket controls, power operated engine hood, rearview camera, enclosed ROPS cab with air conditioning, power heated mirrors, and 20.5R25 tires. In good condition with good tires. (Meter Reads 7,280 Hours) (Fiberglass Damage to Engine Hood) (Unit #B-96) (High Tip Bucket Sells Separately)
- 21 _____ 2016 VOLVO Model L90H Rubber Tired Loader, s/n 623568, powered by Volvo diesel engine and powershift transmission, equipped with hydraulic coupler, front auxiliary hydraulics, power operated engine hood, rearview camera, enclosed ROPS cab with air conditioning, and 20.5R25 tires. In good condition with good tires. (Meter Reads 8,003 Hours) (Unit #B-121) (No Bucket) (High Tip Bucket Sells Separately)
- 22 _____ 2021 VOLVO 10 CY High Tip Bucket, s/n 21140693 (9.2 CY Struck)
- 23 _____ 2012 VOLVO 10 CY (9.6 CY Struck)
- 24 _____ 2003 CASE Model 621D Rubber Tired Loader, s/n JEE0135802, powered by Case diesel engine and powershift transmission, equipped with ACS general purpose loader bucket, ACS hydraulic coupler, front auxiliary hydraulics, ride control, enclosed ROPS cab, and 525/80R25 tires. In fair to poor condition with fair tires. (New fuel injector pump and Rebuilt bucket crowd cylinder) (Transmission Issues – Intermittently Kicks Into Neutral)
- 25 _____ 2015 CASE Model CX210D Hydraulic Excavator, s/n DAC210K7NFS7H1187, powered by Isuzu diesel engine and hydraulic drive, equipped with 9'6" dipper stick, Strickland hydraulic coupler, auxiliary hydraulics, Strickland 48" digging bucket, Strickland 26" hydraulic thumb, rearview camera, enclosed ROPS cab with air conditioning, and 31.5" TBG pads. In good condition with good undercarriage. (Meter Reads 7,460 Hours) (Bucket Poor) (Unit #B-128)
- 26 _____ 2002 CASE Model CX330 Hydraulic Excavator, s/n DAC0733119, powered by Cummins diesel engine and hydraulic drive, equipped with 10'6" dipper stick, auxiliary hydraulics, 60" digging bucket, enclosed ROPS cab, and 31.5" TBG pads. In fair condition with fair to good undercarriage. (Meter Reads 15,189 Hours) (Unit #B-137)
- 27 _____ 1997 HITACHI Model EX200LC-5 Hydraulic Excavator, s/n 14M-84339, powered by Isuzu diesel engine and hydraulic drive, equipped with 9'6" dipper stick, Geith 48" digging bucket, stiff arm bracket, enclosed ROPS cab with air conditioning, and 31.5" TBG pads. In fair condition with fair to good undercarriage. (Meter Reads 06,950 Hours) (Swing Motor Issues – Won't Hold) (Unit #B-120)

- 28_____ Mechanical Stump Shear (Previously mounted on Case CX330)
- 29_____ STRICKLAND Mechanical Stump Shear
- 30_____ 2013 MORBARK Model 6600 Wood Hog Crawler Horizontal Grinder, s/n 186-1149, powered by Cat C32, Tier 2, 1125HP diesel engine, equipped with 17' 6" x 64" infeed with variable speed 5-chain live floor, folding discharge conveyor with magnetic head pulley, reversing fan, remote control, and 27.5" DBG pads. In good condition with good to very good undercarriage. (Meter Reads 7,231 Hours) (Unit #B-130)
- 31_____ 2006 MORBARK Model 6600 Wood Hog Crawler Horizontal Grinder, s/n 186-1087, powered by Cat 3412E, 1000HP reman diesel engine, equipped with 17' 6" x 64" infeed with variable speed 5-chain live floor, folding discharge conveyor with magnetic head pulley, reversing fan, remote control, and 27.5" DBG pads. In good condition with good undercarriage. (7,470 Hours) (ID Plate Obliterated – s/n From List) (Unit #B-131)
- 32_____ 2002 MORBARK Model 1200XL Portable Tub Grinder, s/n 567-514, powered by Cat C-18, 746HP diesel engine, equipped with 12' tub, 36" hydraulic folding discharge conveyor, reversing fan, remote control, tri-axle carrier, (2) hydraulic stabilizers, and 255/70R22.5 tires. In good condition with good tires. (Hour Meter Non-Op) (Oct. 2025 – Replaced Clutch Pack) (Unit #B-132)
- 33_____ 2012 MCCLOSKEY Model 628 Static Tandem Axle Portable Trommel Colorizer, s/n 80647, powered by Cat diesel engine, equipped with 6' x 28' trommel (no screens), Chameleon colorant system with Bredel SPX25 pump, PowerFlex 40 digital dye pump control panel, variable speed feed control, folding discharge conveyor, (4) hydraulic stabilizers, and 315/80R22.5 tires. In good condition with good tires. (Meter Reads 03,750 Hours) (Dec. 2024 – Replaced PowerFlex 40, SPX25 Dye Pump Controller; Feb. 2025 Set Up @ 300 Yards Per Hour)(Unit #B-135)
- 34_____ 2009 MCCLOSKEY Model 621 REG Portable Trommel Screen, s/n 70180, powered by Cat in-line 6 cylinder diesel engine, equipped with 6' x 21' trommel screen, (2) folding discharge conveyors, hydraulic transport wheels, mounted on tri-axle carrier, and 315/80R22.5 tires. In good condition with good tires. (Meter Reads 11,381 Hours) (Commonwealth Verified Year as 2009) (Unit #B-134)
- 35_____ 2018 EDGE Model TS8040 Crawler Stacking Conveyor, s/n 18TS8040739, powered by Cat C2.2 diesel engine, equipped with 80' x 40" double folding conveyor and 16" TBG pads. In good condition with good undercarriage. (Meter Reads 06,039 Hours) (Unit #B-126)
- 36_____ (1 Set) (3) 3/4" Round Screen Grate (6600)
- 37_____ (1 Set) (3) 6" Hex Screen Grate (6600)
- 38_____ (1 Set) (3) 8" Hex Screen Grate (6600)
- 39_____ (1 Set) (3) 1.5" Hex Screen Grate (6600)
- 40_____ (1 Set) (3) 2" Hex Screen Grate (6600)
- 41_____ (1 Set) (3) 1.5" Hex Screen Grate (6600)
- 42_____ (1 Set) (3) 1.5" Hex Screen Grate (6600)
- 43_____ (1) 1.5" Hex Screen Grate (6600)
- 44_____ (1 Set) (2) 8" Round Screen Grate (1200)
- 45_____ (1 Set) (2) 6" x 4" Screen Grate (1200)
- 46_____ (2) Screen Grates – 1.5" Hex and 1.5" Round (1200)
- 47_____ (1 Set) (2) 2" Hex Screen Grate (1200)
- 48_____ (1 Set) (2) 2" Hex Screen Grate (1200)
- 49_____ (1 Set) (2) 1.5" Hex Screen Grate (1200)
- 50_____ (1 Set) (2) 2" Hex Screen Grate (1200)
- 51_____ (1 Set) (2) 2" Hex Screen Grate (1200)
- 52_____ (1 Set) (2) 2" Hex Screen Grate (1200)
- 53_____ (1 Set) (2) 2" Hex Screen Grate (1200)
- 54_____ (1 Set) (2) 1.5" Hex Screen Grate (1200)
- 55_____ (1 Set) (2) 1.5" Hex Screen Grate (1200)
- 56_____ (1 Set) (2) 1.5" Hex Screen Grate (1200)
- 57_____ (1 Set) (2) 1.5" Hex Screen Grate (1200)
- 58_____ (1 Set) (2) 1.5" Hex Screen Grate (1200)
- 59_____ (1 Set) (2) 1.5" Hex Screen Grate (1200)
- 60_____ (1 Set) (2) 1.5" Hex Screen Grate (1200)
- 61_____ (1 Set) (2) 1.5" Hex Screen Grate (1200)

- 62_____ (1 Set) (2) 1.5" Hex Screen Grate (1200)
- 63_____ (1 Set) (2) 1.75" Hex Screen Grate (1200)
- 64_____ (1 Section) Trommel Screen Material – 1/2"
(621)
- 65_____ (1 Section) Trommel Screen Material – 3/8"
(621)
- 66_____ (1 Section) Trommel Screen Material – 3/4"
(621)
- 67_____ (1 Section) Trommel Screen Material – 3/8"
(621)
- 68_____ (1 Section) Trommel Screen Material – 1/2"
(Bent) (621)
- 69_____ (1 Section) Trommel Screen Material – 3/8"
(621)
- 70_____ (1 Section) Trommel Screen Material – 3/8"
(621)
- 72_____ (1 Section) Trommel Screen Material – 5/8"
(621)
- 73_____ (1 Section) Trommel Screen Material – 3/4"
(621)
- 74_____ MCCLOSKEY Trommel Screen Barrel, 5' x
17' (No Screen)
- 75_____ MENARD 22,000 Gallon Portable Frac Tank,
with 11R22.5 tires. In good condition with fair
tires.
- 76_____ 2006 EXTEC Model I-C13 Crawler Impact
Crusher, equipped with KRUPP/HAZEMAG
horizontal shaft impactor, 3-bar rotor mill
(New Blow bars- less than 20 hours), 42"x13'
vibrating pan/grizzly feeder with folding wing
extensions, approx. 50"x37" feed opening,
under-crusher vibrating pan feeder, cross belt
magnet (no belt), folding discharge conveyor
(no belt) (4) hydraulic stabilizers, 14'10"
crawlers, 19.5" TBG pads. (Just under 6,000
hours at time of loss) (Sold In-Absentia –
Located in Orwigsburg, PA. BUYER
responsible for loading and removal) (Fire
Damage – engine caught fire and burned
rearward, toward discharge conveyor. Loss of
engine and all components, operating control
panel, conveyor belting, and hydraulic hoses)
• Good Components: Undercarriage Group;
Vibrating Feeder (recently re-lined);
Horizontal Shaft Impactor Mill (new blow bars
– less than 20 hours); Under-Crusher
Vibrating Pan Feeder; Cross Magnet (no Belt)
- 77_____ EXTEC Tri-Axle Transport Dolly with air ride
suspension and 275/70R22.5 tires. In fair to
good condition with fair tires. (No Title) (Sold
Separately)
- 100_____ (Unit #15-41) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition. with Cover Lids
- 101_____ (Unit #15-39) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition. with Cover Lids
- 102_____ (Unit #15-40) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition. with Cover Lids
- 103_____ (Unit #15-18) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Split Can Dumpster. In good condition.
- 104_____ (Unit #15-46) 15 Cu. Yd., 14' L x 4'10" H
Combo Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.
- 105_____ (Unit #15-27) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.
- 106_____ (Unit #15-42) 15 Cu. Yd., 14' L x 4'10" H
Combo Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.
- 107_____ (Unit #15-34) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.
- 108_____ (Unit #15-19) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.
- 109_____ (Unit #15-13) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.
- 110_____ (Unit #15-05) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.
- 111_____ (Unit #15-20) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.
- 112_____ (Unit #15-17) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.
- 113_____ (Unit #15-37) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.

144_____ (Unit #15-16) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.

145_____ (Unit #15-01) 15 Cu. Yd., 14' L x 4'10" H
Combination Hook & Cable (Hooklift/Rolloff)
Dumpster. In good condition.

146_____ (Unit #20-1) 20 Cu. Yd., 22' L x 52" H Rolloff
Dumpster. In good condition.

147_____ (Unit #20-3) 20 Cu. Yd., 22' L x 54" H Tub
Style Rolloff Dumpster. In good condition.

148_____ (#Unit 30-101) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

149_____ (Unit #30-65) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

150_____ (Unit #30-90) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

151_____ (Unit #30-76) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

152_____ (Unit #30-05) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

153_____ (Unit #30-55) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

154_____ (Unit #30-29) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

155_____ (Unit #30-64) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

156_____ (Unit #30-68) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

157_____ (Unit #30-13) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

158_____ (Unit #30-70) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

159_____ (#Unit 30-109) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

160_____ (#Unit 30-104) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

161_____ (Unit #30-46) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

162_____ (Unit #30-72) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

163_____ (Unit #30-74) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

164_____ (Unit #30-25) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

165_____ (Unit #30-96) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

166_____ (Unit #30-93) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

167_____ (#Unit 30-106) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

168_____ (Unit #30-34) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

169_____ (Unit #30-98) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

170_____ (#Unit 30-107) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

171_____ (Unit #30-88) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

172_____ (Unit #30-86) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

173_____ (Unit #30-42) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

174_____ (#Unit 30-100) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

175_____ (Unit #30-11) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

176_____ (Unit #30-45) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

177_____ (Unit #30-26) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

178_____ (Unit #30-49) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

179_____ (Unit #30-35) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

180_____ (Unit #30-47) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

181_____ (Unit #30-87) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

182_____ (#Unit 30-110) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

183_____(Unit #30-78) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

184_____(Unit #30-52) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

185_____(Unit #30-71) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

186_____(Unit #30-51) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

187_____(#Unit 30-113) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

188_____(Unit #30-60) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

189_____(Unit #30-08) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

190_____(Unit #30-22) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

191_____(Unit #30-27) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

192_____(Unit #30-32) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

193_____(Unit #30-59) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

194_____(Unit #30-40) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

195_____(Unit #30-41) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

196_____(Unit #30-15) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

197_____(Unit #30-28) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

198_____(Unit #30-48) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

199_____(Unit #30-66) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

200_____(Unit #30-69) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

201_____(Unit #30-23) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

202_____(Unit #30-38) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

203_____(Unit #30-97) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

204_____(Unit #30-33) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster (Side Damage)

205_____(Unit #30-91) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

206_____(Unit #30-53) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

207_____(Unit #30-83) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

208_____(Unit #30-36) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

209_____(Unit #30-95) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

210_____(Unit #30-56) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

211_____(Unit #30-43) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

212_____(Unit #30-30) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

213_____(Unit #30-82) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

214_____(Unit #30-61) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

215_____(Unit #30-39) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

216_____(Unit #30-67) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

217_____(Unit #30-54) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

218_____(Unit #30-73) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

219_____(#Unit 30-112) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

220_____(#Unit 30-111) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

221_____(Unit #30-58) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

222_____(Unit #30-108) 30 Cu. Yd., 22' L x 6' H Rolloff
Dumpster. In good condition.

- 223_____ (Unit #30-99) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 224_____ (Unit #30-92) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 225_____ (Unit #30-79) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 226_____ (Unit #30-57) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 227_____ (#Unit 30-103) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 228_____ (Unit #30-89) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 229_____ (Unit #30-17) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 230_____ (Unit #30-75) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 231_____ (Unit #30-16) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 232_____ (Unit #30-21) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 233_____ (#Unit 30-105) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In good condition.
- 234_____ (Unit #30-02) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In fair condition.
- 235_____ (Unit #30-04) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In fair condition.
- 236_____ (Unit #30-01) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In fair condition.
- 237_____ (Unit #30-03) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In fair condition.
- 238_____ (Unit #30-09) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In fair to poor condition.
- 239_____ (Unit #30-06) 30 Cu. Yd., 22' L x 6' H Rolloff Dumpster. In fair to poor condition.
- 240_____ (Unit #40-1) 40 Cu. Yd., 22' L x 90" H Tub Style Rolloff Dumpster. In fair to poor condition.

TIMED AUCTION PORTION BEGINS

- 300_____ CLUB CAR Carryall 1700, 4x4 Utility Vehicle, s/n SD1805-848243, powered by Kubota diesel engine, equipped with 4-passenger, manual dump bed, aluminum frame, and 5,350 lb GVWR. In fair to good condition with good tires. (Meter Reads 883 Hours) (NO TITLE)
- 301_____ CLUB CAR Carryall 1700, 4x4 Utility Vehicle, s/n SD1736-824012, powered by Kubota diesel engine, equipped with 4-passenger, manual dump bed, aluminum frame, and 5,350 lb GVWR. In fair to good condition with good tires. (Meter Reads 1,973 Hours) (NO TITLE)
- 302_____ CLUB CAR Carryall 1700, 4x4 Utility Vehicle, s/n SD1821-874718, powered by Kubota diesel engine, equipped with 4-passenger, manual dump bed, aluminum frame, and 5,350 lb GVWR. In fair to good condition with good tires. (Meter Reads 1,751 Hours) (NO TITLE)
- 303_____ CLUB CAR Carryall 1700, 4x4 Utility Vehicle, s/n SD1736-823994, powered by Kubota diesel engine, equipped with 4-passenger, manual dump bed, and aluminum frame. In fair to good condition with good tires. (Meter Reads 926 Hours) (NO TITLE)
- 304_____ WACKER Model RT Articulated Trench Compactor, s/n unknown, powered by Lombardini diesel, 33" padfoot drums. In fair to good condition. (No Remote) (Unit #B-39)
- 305_____ 28" Mechanical Thumb (Excavator)
- 306_____ 102" Root Rake, with hydraulic grapple
- 307_____ HANDY 67" Scalping Rake (Cat 320)
- 308_____ 2024 R&D Attachment Coupler Bracket (Case CX130)
- 309_____ BODINE 5-Tine Grapple (Excavator)
- 310_____ 2020 CAT CVP40 Plate Compactor, 23" plate (Excavator)
- 311_____ 2020 CAT BA118C Hydraulic Broom, with hydraulic angle (Skid Steer)
- 312_____ UNUSED 2023 TOPCAT Model ECSSRB Tree Shear (Skid Steer)
- 313_____ 100" High-Tip Light Material Bucket (Skid Steer)

- 314_____ 100" High-Tip Light Material Bucket (Skid Steer)
- 315_____ Chain Link Fence Dispenser (Skid Steer)
- 316_____ NEW HOLLAND 66" Grapple Bucket (Skid Steer)
- 317_____ 74" General Purpose Loader Bucket, with teeth (Skid Steer)
- 318_____ BOBCAT 68" General Purpose Loader Bucket (Skid Steer)
- 319_____ BOBCAT 72" General Purpose Loader Bucket (Skid Steer)
- 320_____ UNUSED Hydraulic Trencher Attachment, 52" trenching bar, with dirt chain (Dingo)
- 321_____ UNUSED Hydraulic Trencher Attachment, 52" trenching bar, with dirt chain (Dingo)
- 322_____ 2025 GIYI Hydraulic Mixing Bucket (DINGO)
- 323_____ CP 24" Digging Bucket
- 324_____ Forklift Dump Hopper
- 325_____ Forklift Dump Hopper
- 326_____ Forklift Dump Hopper
- 327_____ HEFTY HOPPER 2 Cu. Yd. Forklift Dump Hopper
- 328_____ Forklift Dump Hopper
- 329_____ UNUSED (In Box) Quonset Hut: 70'x30'x22' includes (8) Arches with Anchor Plates, (2) 13'W x 14'H Doors, PVC Fabric
- 330_____ 275 Gallon Tank, with pneumatic pump
- 331_____ 275 Gallon Tank, with pneumatic pump
- 332_____ 500 Gallon Fuel Tank
- 333_____ Fuel Tank
- 334_____ 1,000 Gallon Fuel Tank
- 335_____ 1,000 Gallon Fuel Tank
- 336_____ Step Fuel Tank
- 337_____ Skid Mounted Pneumatic Luber, with gas powered air compressor
- 338_____ (2) Gas Powered Horizontal Air Compressors
- 339_____ CASE 48" Digging Bucket (Damaged)
- 340_____ (34) Used Truck Tires
- 341_____ Wire Rope Slings
- 342_____ KINEDYNE 84.6" to 95" Beam Load Bars
- 343_____ Shelving
- 344_____ Steel Plate and Poly Mat
- 345_____ MITSUBISHI Model FGC18, 3,500 Lb Solid Tired Forklift, s/n AF81B-53450, powered by LP gas engine and shuttle transmission, equipped with 190" 3-stage mast, power side shift, 58" forks, and FOPS canopy. In good condition with good tires. (Meter Reads 09,940 Hours)
- 346_____ RIDGID 1822 Portable Power Threader
- 347_____ 2019 MILLER Dynasty 400 TIG Welder, s/n MK 030273L
- 348_____ 2019 MILLER Dynasty 400 TIG Welder, s/n MK030652L
- 349_____ 2014 MILLER Dynasty 280DX TIG Welder, s/n ME200091L
- 350_____ MILLER Bobcat 250 Gas Welder (Not Running)
- 351_____ KARCHER 3000 PSI Gas Powered Pressure Washer, Honda gas, with heat
- 352_____ BLUE VIPER Gas Powered Pressure Washer, with heat (Engine Seized)
- 353_____ SHARK 3500 PSI Pressure Washer, with heat (Gas Engine Seized)
- 354_____ Portable Pressure Washer, gas powered
- 355_____ Gas Powered Air Compressor, Predator gas engine, 30 gal horizontal tank
- 356_____ TOKU TPB-60 Pneumatic Paving Breaker
- 357_____ TOKU TPB-60 Pneumatic Paving Breaker
- 358_____ TOKU TPB-60 Pneumatic Paving Breaker
- 359_____ TOKU TPB-60 Pneumatic Paving Breaker
- 360_____ TOKU TPB-60 Pneumatic Paving Breaker
- 361_____ 2020 ATLAS COPCO Pneumatic Paving Breaker

362_____ (2) Pneumatic Paving Breakers	392_____ MILWAUKEE Battery Powered Luber
363_____ UNUSED Breaker Steel	393_____ Bench Vise
364_____ UNUSED Breaker Steel	394_____ Assorted Combination Wrenches
365_____ UNUSED Breaker Steel	395_____ MUNCIE PTO
366_____ SEAL MASTER Tar Pot	396_____ Metal Shelf
367_____ (2) 3" and (2) 2" Gas Powered Pumps	397_____ Shop Bench, with contents
368_____ AMP 10,000 Watt Generator, Kohler gas	398_____ Shop Bench, with contents
369_____ (1 Pallet) (Mostly UNUSED) Air Hose	399_____ Shop Bench, with contents
370_____ (1 Pallet) Air Hose	400_____ Hardware Bins
371_____ WESCO Pallet Jack	401_____ Metal Shop Bench/Shelving Unit
372_____ Pallet Jack	402_____ CMC MCD-20 Mulch Colorant Metering Pump with BREDEL Electric Pump and PowerFlex 40 Digital Controller
373_____ Banding Cart and Accessories	403_____ CMC MCD-20 Mulch Colorant Metering Pump with BREDEL Electric Pump and PowerFlex 40 Digital Controller
374_____ Barrel and Bottle Carts	404_____ Hammer Set and Rods (Morbark 6600)
375_____ GRAY 50,000 Lb Pneumatic Floor Jack	405_____ Hammer Set and Rods (Morbark 1200XL)
376_____ Floor Jack and Assorted Bottle Jacks	406_____ Rollers and Accessories (Grinders)
377_____ (3) Jack Stands	407_____ (8) UNUSED Trommel Screen Brushes
378_____ FRONTIER Portable Tool Chest	408_____ Conveyor Belt
379_____ US GENERAL Portable Toolbox	409_____ Machine Glass
380_____ (3) CRAFTSMAN Toolboxes	410_____ Thumb Brackets and Assorted Parts
381_____ 3/4" Impact Sockets	411_____ JOB Box and Tarp
382_____ Assorted Sockets	412_____ Shop Fan, Heater, and Radio
383_____ PITTSBURGH 3/4" Socket Set	413_____ Assorted Parts
384_____ 1" Pneumatic Impact Wrench	414_____ Fuel Cans
385_____ 1" Pneumatic Impact Wrench	415_____ Ratchet Straps and Light Bar
386_____ (5) Impact Wrenches	416_____ Electric Cord and Air Hose
387_____ Assorted Pneumatic Tools	417_____ (6) Truck Rims
388_____ HERCULES Dual Wheel Bench Grinder	
389_____ Electric Grinders	
390_____ (3) Saws and (1) Drill	
391_____ Pneumatic Saw	

Thank You For Participating!